

METAL STAMPINGS &
 PEWTER CASTINGS

SHOES

C BEFORE # = CASTING
 * = DOUBLESIDED



C6141
 COL: 1,2,7



*C6148
 COL: 1,2,7



*C9998
 COL: 1,2,7



*C9999
 COL: 1,2,7



*C9995
 COL: 1,2



*C6168
 COL: 1,2,7



*C9996
 COL: 1,2



*C1893
 COL: 1,2,7



*C6161
 COL: 1,2



*C6139
 COL: 1,2,7



*C6169
 COL: 1,2,7



*C6162
 COL: 1,2



*C6165
 COL: 1,2



C6200
 COL: 1,2,7



*C6177
 COL: 1,2



*C6176
 COL: 1,2



1894
 COL: 1,2



1007
 COL: 1,2



*C9988
 COL: 1,2,7



C9989
 COL: 1,2,7



C9997
 COL: 1,2,7



C9990
 COL: 1,2,7



*C6175
 COL: 1,2,7